GENERAL INFORMATION		
SUBMITTED DATE	08/13/2021	
ORDER #		
PUMPER/GAUGER		
LATITUDE	48.344503	
LONGITUDE	-103.040979	
CUSTOMER REPRESENTATIVE	MARLON HARRY	
UNIT DESIGNATION	1100-500-306	
API NUMBER		
UNIT SERIAL NUMBER	03209-320-0870	
GEAR REDUCER SERIAL NUMBER	9-729	
UNIT NOT IN OPERATION	NO	
UNIT NOT IN OPERATION DESCRIPTION		
UNIT NOT INSPECTED	NO	
UNIT NOT INSPECTED DESCRIPTION		
PRIMARY JOB TASK / PURPOSE FOR BEING ON-SITE	INSPECTION	
MANUFACTURE DATE		
CURRENT INSPECTION DATE	8/13/2021 8:56:08 AM	
THIS IS A UNIT TRANSFER	NO	
NEXT INSPECTION ON		
BARCODE / ASSET NUMBER		
CUSTOMER SPECIFIC INFORMATION		
UNIT SHUT DOWN UPON ARRIVAL	NO	
UNIT SHUT DOWN FOR INSPECTION	NO	
THIS IS A NEW UNIT INSTALLATION	NO	

<sup>© 2021</sup> Weatherford All Rights Reserved Proprietary and Confidential. This document is copyrighted and contains valuable proprietary and confidential information, whether patentable or unpatentable, of Weatherford. Recipients agree the document is loaned with confidential restrictions, and with the understanding that neither it nor the information contained therein will be reproduced, used or disclosed in whole or in part for any purpose except as may be specifically authorized in writing by Weatherford.

GENERAL INFORMATION		
INSTALLATION DATE		
WEATHERFORD INSPECTOR	BROOKS, BRANDON	
I HAVE REVIEWED THE ENERGY ISOLATION AND PREVENTATIVE MAINTENANCE TWIS AS APPLICABLE	YES	
No	DTES	
LIST ALL DETAILS OF THE INSPECTION, MAINTENANCE PROCEDURES OF NOTE	UNIT LAYING OVER IN ND YARD. DAMAGE TO FRONT COUNTERWEIGHT DOORS UPPERS AND LOWERS. SPEED SENTRY MISSING. GEARBOX HUB MISSING. BELT GUARD AND LADDER CAGE HARDWARE MISSING. HOLE IN FRONT OF TOWER. LOAD BELT HAS FRAYED EDGE ON LEFT SIDE. CROWN HOOD LATCH DAMAGED AND NEED REPLACED. MISSING POWER BAND FOR MOTOR. COULDN'T OPEN DOORS DUE TO THE DAMAGE TO CHECK GUIDE WHEELS. WIND GUARD HARDWARE MISSING. UNIT IS LAID OVER COULD NOT DO A FULL INSPECTION.	
FACILI	TY SIGNS	
FACILITY SIGNS MISSING	REGULATED CONFINED SPACE	
SEALS AN	D BEARINGS	
RIGHT TOP DRUM BEARING	GOOD CONDITION	
RIGHT TOP DRUM SEAL	REPAIR/REPLACE	
LEFT TOP DRUM BEARING	GOOD CONDITION	
LEFT TOP DRUM SEAL	GOOD CONDITION	
TOP SPROCKET BEARINGS	GOOD CONDITION	
TOP SPROCKET SEALS	GOOD CONDITION	
TRAVERSING MECHANISM BEARINGS 1	CONDITION REQUIRES UNIT SHUTDOWN	
TRAVERSING MECHANISM SEALS 2	CONDITION REQUIRES UNIT SHUTDOWN	
BRAKING SYSTEM		
EMERGENCY BRAKE ADJUSTMENTS MADE	GOOD, NO ADJUSTMENTS REQUIRED	
MANUAL BRAKE ADJUSTMENTS MADE	GOOD, NO ADJUSTMENTS REQUIRED	

<sup>© 2021</sup> Weatherford All Rights Reserved Proprietary and Confidential. This document is copyrighted and contains valuable proprietary and confidential information, whether patentable or unpatentable, of Weatherford. Recipients agree the document is loaned with confidential restrictions, and with the understanding that neither it nor the information contained therein will be reproduced, used or disclosed in whole or in part for any purpose except as may be specifically authorized in writing by Weatherford.

# Weatherford® Pumping Unit Inspection #E234943-20210813085608 CUSTOMER SERVICE LOCATION LEASE WELL NUMBER

Williston, ND

ND Yard

ND Yard

ND Corporation

BRAKING SYSTEM		
BRAKE RODS FUNCTIONING PROPERLY	YES	
MANUAL BRAKE PAD THICKNESS	FAIR	
EMERGENCY BRAKE PAD THICKNESS	FAIR	
BRAKE ROTOR CONDITION	GOOD CONDITION	
EMERGENCY ACTUATOR OPERABLE 3	NO	
MANUAL BRAKE TENSION	GOOD	
EMERGENCY BRAKE TENSION	GOOD	
PROXIMITY SENSOR AIR GAP	GOOD	
GROUND LEVEL		
LOAD BELT PINS AND KEEP BARS	GOOD CONDITION	
BRIDLE / BANANA BAR	GOOD CONDITION	
POLISHED ROD CONDITION 4	CONDITION REQUIRES UNIT SHUTDOWN	
POLISHED ROD LINER CONDITION	NA	
ROD ROTATOR INSTALLED	NO	
ROD ROTATOR FUNCTIONAL		
AMPS ON UPSTROKE (ROD AMPS)		
AMPS ON DOWNSTROKE (WEIGHT AMPS)		
AMP OFFAGE		
UNIT BALANCE	NOT CHECKED	
STROKES PER MINUTE	0.0	
GAS ENGINE APPEARS TO BE STRAINING		
WEATHERFORD REPRESENTATIVE HAS BEEN CONTACTED		
CUSTOMER HAS BEEN CONTACTED		
ADDED COUNTERWEIGHT	NO	

<sup>© 2021</sup> Weatherford All Rights Reserved Proprietary and Confidential. This document is copyrighted and contains valuable proprietary and confidential information, whether patentable or unpatentable, of Weatherford. Recipients agree the document is loaned with confidential restrictions, and with the understanding that neither it nor the information contained therein will be reproduced, used or disclosed in whole or in part for any purpose except as may be specifically authorized in writing by Weatherford.

CUSTOMER	SERVICE LOCATION	LEASE	WELL NUMBER
ND Corporation	Williston, ND	ND Yard	ND Yard

GROUND LEVEL		
POUNDS OF WEIGHT ADDED		
UNIT OPERATING WITH VSD	YES	
VSD MAKE	OTHER	
PEAK LOAD SHOWN ON VFD	NOT SELECTED	
UNIT OPERATING IN RACE TRACK MODE/TRIM SPEED ENABLED	NO	
REVERSAL TOP OF STROKE SPM		
REVERSAL BOTTOM OF STROKE SPM		
UPSTROKE SPM		
DOWNSTROKE SPM		
MURPHY VIBRATION SENSOR 5	CONDITION REQUIRES UNIT SHUTDOWN	
SPEED SENTRY MODEL		
OVERSPEED SET POINT	0.0	
UNDERSPEED SET POINT	0.0	
SPEED SENTRY MEMORY RECORDING	NO	
OVERSPEED SHUTDOWN	NOT WORKING	
UNDERSPEED SHUTDOWN	NOT WORKING	
CUSTOMER SPECIFIC SPEED SENTRY SHUTDOWN	NOT WORKING	
TOWER BASE TO SKID BOLTS	REPLACEMENT REQUIRED	
ELECTRIC MOTOR GREASED	NA	
RUBBER BOOT	GOOD CONDITION	
ROTAFLEX TOWER CONDITION	GOOD CONDITION	
OIL LEAKS	NONE	
OIL LEAKS OTHER DESCRIPTION		

<sup>© 2021</sup> Weatherford All Rights Reserved Proprietary and Confidential. This document is copyrighted and contains valuable proprietary and confidential information, whether patentable or unpatentable, of Weatherford. Recipients agree the document is loaned with confidential restrictions, and with the understanding that neither it nor the information contained therein will be reproduced, used or disclosed in whole or in part for any purpose except as may be specifically authorized in writing by Weatherford.

GROUND LEVEL		
CONFIRMED SET BACK DISTANCE(MEASURED FROM THE CENTER OF THE WELLBORE TO FRONT OF CONCRETE BASE WITH STRING LINE)	NOT CHECKED	
UNIT ALIGNMENT	IN ALIGNMENT	
UNIT LEVEL	LEVEL	
UPPER LADDER & CAGE CONDITION	GOOD CONDITION	
LOWER LADDER & CAGE CONDITION	GOOD CONDITION	
CARRIER BAR CONDITION	GOOD CONDITION	
TIE-DOWNS CONDITION	GOOD CONDITION	
CONCRETE BASE CONDITION	GOOD CONDITION	
NOSE PAD CONDITION	NA	
PIER CONDITION	NA	
I-BEAM CONDITION	NA	
LOAD BELT CONDITION (VISUAL VIEW FROM OUTSIDE OF UNIT)	REPLACEMENT REQUIRED	
STRUCTUR	AL CRACKS	
ARE THERE STRUCTURAL CRACKS PRESENT?	NO	
IF PRESENT, HAVE STRUCTURAL CRACKS BEEN IDENTIFIED BY PAINT?		
DESCRIBE SPECIFIC LOCATION OF STRUCTURAL CRACK(S) (ADD IMAGES OF STRUCTURAL CRACKS PRESENT TO LAST PAGE OF INSPECTION)		
GEAR REDUCER BEARINGS/BUSHINGS		
LOW SPEED CONDITION	NEEDS FURTHER INSPECTION	
INTERMEDIATE SPEED CONDITION	NEEDS FURTHER INSPECTION	
HIGH SPEED CONDITION	NEEDS FURTHER INSPECTION	

<sup>© 2021</sup> Weatherford All Rights Reserved Proprietary and Confidential. This document is copyrighted and contains valuable proprietary and confidential information, whether patentable or unpatentable, of Weatherford. Recipients agree the document is loaned with confidential restrictions, and with the understanding that neither it nor the information contained therein will be reproduced, used or disclosed in whole or in part for any purpose except as may be specifically authorized in writing by Weatherford.

GEAR REDUCER SEALS/GASKETS			
LOW SPEED CONDITION	NEEDS FURTHER INSPECTION		
INTERMEDIATE SPEED CONDITION	NEEDS FURTHER INSPECTION		
HIGH SPEED CONDITION	NEEDS FURTHER INSPECTION		
GEAR CO	ONDITION		
LOW SPEED GEAR	NEEDS FURTHER INSPECTION		
LOW SPEED PINION	NEEDS FURTHER INSPECTION		
HIGH SPEED GEAR	NEEDS FURTHER INSPECTION		
HIGH SPEED PINION	NEEDS FURTHER INSPECTION		
OIL CONDITION			
OIL LEVEL	LOW		
OIL CONDITION	REQUIRES REPLACEMENT OF ALL OIL		
PRIME	MOVER		
TYPE (GAS/ELECTRIC)	ELECTRIC		
BRAND			
MODEL	BALDOR		
SERIAL NUMBER	C0212045045		
FRAME NUMBER	445T		
RPM	1125		
HORSEPOWER	100		
SHEAVE DIAMETER (INCHES)	16		
BELT CONDITION	REPLACEMENT REQUIRED		
SHAFT CONDITION	GOOD CONDITION		
SHAFT SIZE (INCHES)	3 3/8		
GEAR REDUCER SHEAVE CONDITION	GOOD CONDITION		

<sup>© 2021</sup> Weatherford All Rights Reserved Proprietary and Confidential. This document is copyrighted and contains valuable proprietary and confidential information, whether patentable or unpatentable, of Weatherford. Recipients agree the document is loaned with confidential restrictions, and with the understanding that neither it nor the information contained therein will be reproduced, used or disclosed in whole or in part for any purpose except as may be specifically authorized in writing by Weatherford.

CUSTOMER	SERVICE LOCATION	LEASE	WELL NUMBER
ND Corporation	Williston, ND	ND Yard	ND Yard

PRIME MOVER			
GEAR REDUCER SHEAVE DIAMETER (INCHES)	20		
GAS ENGINE OIL USED (GALLONS)			
GAS ENGINE OIL REQUIRED FILTERING			
OIL SAMPLE TAKEN			
INSIDE (FRONT) COUNTERWEIGHT DOORS			
FRONT COUNTERWEIGHT ROTAFLEX DOORS CONDITION	REPAIR REQUIRED		
FRONT UPPER COUNTERWEIGHT ROTAFLEX DOORS CONDITION	REPAIR REQUIRED		
REMOVED SHIPPING BLOCKS BETWEEN TOWER BEAM AND COUNTERWEIGHT BOX DURING INSTALLATION	YES		
OIL SUMP RESERVOIR	CLEANING AND NEW OIL REQUIRED		
PROPER OIL LEVEL OF SUMP	ADDITIONAL OIL REQUIRED		
SUMP OILING SYSTEM FREE OF OBSTRUCTIONS AND PROPERLY OILING	REPAIR REQUIRED		
INTERNAL LOAD BELT CONDITION AND CONNECTION TO WEIGHT BOX, LOAD BELT PINS	GOOD CONDITION		
BELT AND METAL SHAVINGS PRESENT INSIDE OF TOWER	NO		


<sup>© 2021</sup> Weatherford All Rights Reserved Proprietary and Confidential. This document is copyrighted and contains valuable proprietary and confidential information, whether patentable or unpatentable, of Weatherford. Recipients agree the document is loaned with confidential restrictions, and with the understanding that neither it nor the information contained therein will be reproduced, used or disclosed in whole or in part for any purpose except as may be specifically authorized in writing by Weatherford.

# Pumping Unit Inspection #E234943-20210813085608

CUSTOMER	SERVICE LOCATION	LEASE	WELL NUMBER
ND Corporation	Williston, ND	ND Yard	ND Yard

# **GUIDE WHEELS**

GUIDE
CONDITION REQUIRES UNIT SHUTDOWN



COUNTERWEIGHT BOX	
COUNTERWEIGHT BOX IS PROPERLY ALIGNED INSIDE OF THE TOWER	NO
SWIVEL SHAFT (INCHES)	
DRIVE SPROCKET (INCHES)	

CUSTOMER	SERVICE LOCATION	LEASE	WELL NUMBER
ND Corporation	Williston, ND	ND Yard	ND Yard

COUNTERWEIGHT BOX			
DRIVE SPROCKET CONDITION	REPAIR REQUIRED		
LOAD BELT PIN AND SNAP RINGS CHECKED	NO		
DRIVE CHAIN TENSION CHECKED	NO		
DRIVE CHAIN TENSION ADJUSTED	NOT REQUIRED		
DRIVE CHAIN SIDE TO SIDE DEFLECTION (IN INCHES)	<1"		
DRIVE CHAIN CONDITION	CONDITION REQUIRES UNIT SHUTDOWN		
SWIVEL SHAFT CONDITION	REPAIR REQUIRED		
CARRIAGE ASSEMBLY CONDITION 6	CONDITION REQUIRES UNIT SHUTDOWN		
FRONT CARRIAGE WHEELS CONDITION	REPAIR REQUIRED		
FRONT CARRIAGE WHEEL BEARINGS CONDITION	NOT CHECKED		
VERIFY CARRIAGE FRAME BOLTS ARE TORQUED TO 250 FT. LBS. (8 EACH)	REPAIR REQUIRED		
CARRIAGE FRAME BOLTS CONDITION	NOT CHECKED		
ALL DOORS PROPERLY SECURED AFTER PM COMPLETION	YES		
ALL DOORS NOT PROPERLY SECURED AFTER PM COMPLETION EXPLANATION			
DOORS SECURED WITH ZIP-TIE, LOCK, OR NUMBERED SEAL (IF REQUIRED BY CUSTOMER OR REGION)	NA		
INSIDE (BACK) PANELS	ABOVE GEAR REDUCER		
CHAIN PINS CONDITION	REPAIR REQUIRED		
PIN BOLTS AND RETAINING BAR CONDITION	REPAIR REQUIRED		
SWIVEL SHAFT (KNUCKLE) CONDITION	REPAIR REQUIRED		
BACK CARRIAGE WHEELS CONDITION	REPAIR REQUIRED		
BACK CARRIAGE WHEEL BEARINGS CONDITION	NOT CHECKED		
INSIDE M	ID-TOWER		
MID-TOWER DOORS AND ENCLOSURE CONDITION	GOOD CONDITION		

<sup>© 2021</sup> Weatherford All Rights Reserved Proprietary and Confidential. This document is copyrighted and contains valuable proprietary and confidential information, whether patentable or unpatentable, of Weatherford. Recipients agree the document is loaned with confidential restrictions, and with the understanding that neither it nor the information contained therein will be reproduced, used or disclosed in whole or in part for any purpose except as may be specifically authorized in writing by Weatherford.

CUSTOMER	SERVICE LOCATION	LEASE	WELL NUMBER
ND Corporation	Williston, ND	ND Yard	ND Yard

INSIDE MID-TOWER			
TOP SPROCKET LUBRICATED	NO		
TOP SPROCKET ASSEMBLY CONDITION	GOOD CONDITION		
GREASE ADDED TO TOP SPROCKET	NO		
BEARING NUTS AND LOCKER WASHERS CONDITION	GOOD CONDITION		
TOP SPROCKET ASSEMBLY CHECKED FOR CRACKS AND BENDS IN TUBING	NONE PRESENT		
ADJUSTMENT BOLTS AND JAM NUTS CONDITION	GOOD CONDITION		
DRIVE CHAIN RETAINING PINS CONDITION	CONDITION REQUIRES UNIT SHUTDOWN		
MEASUREMENT FROM CENTER OF THE TOP SPROCKET TO THE OUTSIDE EDGE OF THE TOWER BEAM FLANGE (SHOULD BE 3")	3 INCHES		
TOP TOWER			
HINGE PINS CHECKED BEFORE OPENING THE CROWN HOOD	YES		
CROWN HOOD HINGE PINS CONDITION (HINGE PINS ON THE TOP COVER INSPECTED BEFORE OPENING THE CROWN HOOD)	GOOD-SAFE TO OPEN CROWN HOOD		
ROLLER DRUM SIDE PLATE CONDITION	GOOD CONDITION		
PILLOW BLOCK BEARING SEALS CONDITION	REPAIR REQUIRED		
ROLLER DRUM GREASED	NO		
TOP DRUM LEAKING GREASE	YES		
TOP DRUM BEARINGS CONDITION	GOOD CONDITION		
METAL SHAVINGS FOUND ON PILLOW BLOCK HOUSING	NO		
ROLLBACK SYSTEM			
TYPE OF ROLLBACK SYSTEM	NA		
ROLLBACK SYSTEM CONDITION			
HYDRAULIC FLUID LEVEL			

<sup>© 2021</sup> Weatherford All Rights Reserved Proprietary and Confidential. This document is copyrighted and contains valuable proprietary and confidential information, whether patentable or unpatentable, of Weatherford. Recipients agree the document is loaned with confidential restrictions, and with the understanding that neither it nor the information contained therein will be reproduced, used or disclosed in whole or in part for any purpose except as may be specifically authorized in writing by Weatherford.

Weatherford <sup>®</sup>			
Pumping Unit Inspection #E234943-20210813085608			
CUSTOMER	SERVICE LOCATION	LEASE	WELL NUMBER
ND Corporation	Williston, ND	ND Yard	ND Yard

ROLLBACK SYSTEM			
BUMP CHECK MOTOR TO CONFIRM PROPER ELECTRIC WIRING OF ROLLBACK SYSTEM			
RU	IST		
EXCESSIVE RUST PRESENT	NO		
RUST PRESENCE LOCATION			
COMPLETION CONFIRMATION			
MAINTENANCE STICKER WITH CREW AND DATE INSTALLED ON THE TOWER	NO		
MAINTENANCE STICKER INSTALLED DURING INSPECTION	NO		
ADDITIONAL ITEMS FOUND REQUIRING ATTENTION	NO		
SPECIFICS OF ADDITIONAL ITEMS FOUND			
UNIT CONDITIONS WARRANT CONTINUED SHUTDOWN. CUSTOMER HAS BEEN NOTIFIED.	YES		

IMA	GES
TOTAL NUMBER OF IMAGES	8

<sup>© 2021</sup> Weatherford All Rights Reserved Proprietary and Confidential. This document is copyrighted and contains valuable proprietary and confidential information, whether patentable or unpatentable, of Weatherford. Recipients agree the document is loaned with confidential restrictions, and with the understanding that neither it nor the information contained therein will be reproduced, used or disclosed in whole or in part for any purpose except as may be specifically authorized in writing by Weatherford.

# IMAGES




LEASE SIGN UNIT SERIAL NUMBER


# Pumping Unit Inspection #E234943-20210813085608

CUSTOMER	SERVICE LOCATION	LEASE	WELL NUMBER
ND Corporation	Williston, ND	ND Yard	ND Yard

#### **IMAGES**



GEAR REDUCER SERIAL NUMBER



PRIME MOVER SERIAL NUMBER


# Pumping Unit Inspection #E234943-20210813085608

CUSTOMER	SERVICE LOCATION	LEASE	WELL NUMBER
ND Corporation	Williston, ND	ND Yard	ND Yard

#### **IMAGES**



FRONT COUNTERWEIGHT ROTAFLEX DOORS



FRONT UPPER COUNTERWEIGHT ROTAFLEX DOORS

### Pumping Unit Inspection #E234943-20210813085608

CUSTOMER	SERVICE LOCATION	LEASE	WELL NUMBER
ND Corporation	Williston, ND	ND Yard	ND Yard

#### **IMAGES**





**ROTAFLEX TOWER** 

CROWN HOOD HINGE PINS

#### **NOTES:**

1 TRAVERSING MECHANISM BEARINGS - NOTES			
VALUE CONDITION REQUIRES UNIT SHUTDOWN	<b>REPORTED</b> 8/13/2021	CURRENT STATE IN PROGRESS	

#### 8/23/2021 4:59 PM E007568

UNABLE TO CHECK CARRIAGE ASSY. WEIGHT BOX IS AT THE BOTTOM.

### Pumping Unit Inspection #E234943-20210813085608

CUSTOMER	SERVICE LOCATION	LEASE	WELL NUMBER
ND Corporation	Williston, ND	ND Yard	ND Yard

2 TRAVERSING MECHANISM SEALS - NOTES		
VALUE CONDITION REQUIRES UNIT SHUTDOWN	REPORTED 8/13/2021	CURRENT STATE IN PROGRESS

#### 8/23/2021 5:00 PM E007568

WEIGHT BOX IS AT THE BOTTOM WAS NOT ABLE TO INSPECT CARRIAGE ASSY.

#### **3 EMERGENCY ACTUATOR OPERABLE - NOTES**

VALUE	REPORTED	CURRENT STATE
NO	8/13/2021	IN PROGRESS

#### 8/23/2021 5:01 PM E007568

NO POWER TO THE UNIT NOT ABLE TO CHECK E-BRAKE

### **4 POLISHED ROD - NOTES**

VALUE CONDITION REQUIRES UNIT SHUTDOWN	<b>REPORTED</b> 8/13/2021	CURRENT STATE IN PROGRESS
--	---------------------------	---------------------------

#### 8/23/2021 5:02 PM E007568

NO P-ROD

### **5 MURPHY VIBRATION SENSOR - NOTES**

VALUE CONDITION REQUIRES UNIT SHUTDOWN	<b>REPORTED</b> 8/13/2021	CURRENT STATE IN PROGRESS
--	---------------------------	---------------------------

### 8/23/2021 5:04 PM E007568

NO POWER TO CHECK VIB

#### **6 CARRIAGE ASSEMBLY CONDITION - NOTES**

I CONDITION REQUIRES LINIT	<b>REPORTED</b> 8/13/2021	CURRENT STATE IN PROGRESS
----------------------------	---------------------------	---------------------------

#### 8/23/2021 5:52 PM E007568

UNABLE TO CHECK UNIT IS STACKED OUT

<b>Weatherford®</b>			
Pumping Unit Inspection #E234943-20210813085608			
CUSTOMER	SERVICE LOCATION	LEASE	WELL NUMBER
ND Corporation	Williston, ND	ND Yard	ND Yard

<sup>© 2021</sup> Weatherford All Rights Reserved Proprietary and Confidential. This document is copyrighted and contains valuable proprietary and confidential information, whether patentable or unpatentable, of Weatherford. Recipients agree the document is loaned with confidential restrictions, and with the understanding that neither it nor the information contained therein will be reproduced, used or disclosed in whole or in part for any purpose except as may be specifically authorized in writing by Weatherford.