

## IRG-19-143 Inventory

Lot 1					
Item	MFG	Size	Vin	Plate	Comments
Front End Loader	Volvo	-	-	-	Has not been run in a year, but ran fine before. Comes with snow plow blade attachment.

Lot 2					
Item	MFG	Size	Vin	Plate	Comments
Crane	Linkbelt	60 ton	-	-	Has not been run in a year, but ran fine before. Good condition otherwise.

Lot 3					
Item	MFG	Size	Vin	Plate	Comments
Fuel Truck	Sterling	10,300 Liter	2FZ6MJBB8XAB52650	RZ1073	Rear end in bad need of repair, front axle is out of alignment due to rear end repair issues. Tank passed all inspections. Received interior welding between bulkheads in 2018. IOL# 178

Lot 4					
Item	MFG	Size	Vin	Plate	Comments
Pick up Truck	GMC Sierra	1/2 Ton	1GCEC14WXVZ216864	3957HS	Rotted Frame IOL# 130
Pick up Truck	GMC Sierra	1/2 Ton	2GCEC19V431187155	5724LJ	Rotted Frame IOL# 20305
Pick up Truck	Chevrolet Silverado	1/2 Ton	1GCEC14XX3163152	4822MD	Rotted Frame IOL# 23006
Pick up Truck	GMC Sierra	1/2 Ton	1GTEC14W1YE284738	RZ1073	Rotted Frame IOL# 396
Pick up Truck	GMC Sierra	1/2 Ton	1GCEC14WXYE285189	1004KR	Rotted Frame IOL# 386
Van	-	-	-	-	Involved in front end collision two years ago, body otherwise in good condition. Hasn't ran in two years. IOL# 40727

SELLER DOES NOT BIND ITSELF TO AWARD A SALES AGREEMENT TO THE HIGHEST BIDDER. GOODS BEING OFFERED FOR SALE MAY NOT NECESSARILY BE AWARDED FOR SALE AFTER THE SUBSEQUENT ANALYSIS OF BIDS. SELLER RESERVES THE RIGHT TO WITHDRAW ANY ITEM FROM THE LOT ON OFFER.